Mechanics of Materials

Lecture 4

Mechanical Properties of Materials (1)

Mohamad Fathi GHANAMEH



الجائعــــــة الدوليــــــة للربــــــاد boO∧oLt+ +oXOo+IIol+ I QQOoE Jniversité Internationale de Rabat



Lecture Objectives

- Show relationship of stress and strain using experimental methods to determine stressstrain diagram of a specific material
- Discuss the behavior described in the diagram for commonly used engineering materials



 ✓ Discuss the mechanical properties and other test related to the development of mechanics of materials



الجامعــــــة الدوليــــــة للربــــــاد @∧ه⊔٤+ +ه⊼Oه۲۰ها+ I QQ⊖هE Jniversité Internationale de Rabat





Lecture Outline

- Classification of Materials
- Properties of Materials
- ✓ Levels of Structure



- ✓ The Tension and Compression Test
- ✓ Stress-Strain Diagram.
- ✓ Stress-Strain Behavior of Ductile and Brittle Materials.



الجاوعـــــــة الدوليــــــة للزبــــــاد ⊙∩₀LՀ+ +₀XO₀YN₀I+ I QQ⊖₀E Iniversité Internationale de Rabat





There are deferent ways of classifying materials. One way is to describe five groups:

1. metals and alloys;

- 2. ceramics, glasses, and glass-ceramics;
- 3. polymers (plastics);
- 4. semiconductors;
- 5. Biomaterials; and
- 6. composite materials.



الجارعــــــــــة الدوليــــــة للربــــــاد ⊙∧₀UՀ+ +₀XO₀۲೫₀I+ I QQ⊖₀E Iniversité Internationale de Rabat





Metals

 good conductors of electricity and heat lustrous appearance susceptible to corrosion •strong, but deformable



Ceramics & Glasses •thermally and electrically insulating •resistant to high temperatures and harsh environments •hard, but brittle

Polymers

•very large molecules •low density, low weight maybe extremely flexible







+°OV°T4+ +°XO°AN9+ I OOO°E Université Internationale de Rabat





Biomaterials •implanted in human body •compatible with body tissues



Semiconductors •electrical properties between conductors and insulators •electrical properties can be precisely controlled

Intel Pentium 4

Composites •consist of more than one material type •designed to display a combination of properties of each component



fiberglass surfboards



الجارعــــــــة الدوليـــــــة للربــــــاط +₀O∧₀LՀ+ +₀XO₀YN₀l+ I QQO₀E Université Internationale de Rabat







Properties of Materials

- 1. Chemical Properties
- 2. Physical Properties
- 3. Mechanical Properties



الجاوعــــــة الدوليــــــة للربـــــاط +₀⊙∧₀⊔Հ+ +₀ヌO₀Yłl₀I+ I QQ⊖₀E Université Internationale de Rabat





Chemical Properties

- \checkmark how a material interacts with another material
- ✓ "social" behavior
- ✓ response to other matter (or lack of response)
- ✓ reactions







Chemical Properties

- ✓ Examples:
 - ✓ burning
 - \checkmark reaction with acid
 - ✓ reaction with water
 - ✓ corrosion/rusting/oxidation
 - ✓ others????









الجاوعــــــة الدوليــــــة للربـــــاط +₀⊙∧₀⊔Հ+ +₀ヌO₀∀۱₀I+ I QQ⊖₀E Université Internationale de Rabat



Physical Properties

- ✓ characteristics it possesses by itself (in and of itself)
- ✓ "personal" traits
- \checkmark response to energy



الجاوعــــــة الدوليــــــة للربـــــاط +₀⊙∧₀⊔Հ+ +₀ヌO₀۲೫₀I+ I QQ⊖₀E Université Internationale de Rabat



Physical Properties

- ✓ color
- ✓ size
- ✓ melting point
- ✓ boiling point
- ✓ Solubility
- ✓ Electrical Conductivity
- ✓ Thermal Conductivity

- ✓ Response to light
- ✓ luster
- ✓ density
- ✓ magnetism
- ✓ odor
- ✓ viscosity



Mechanical Properties

Response to force or stress



الجاوعـــــــة الدوليــــــة للربـــــاط +ه،٢٥،٥٤ + اله٧٩،٥٢ المالاه،٢٥،٥٤ Université Internationale de Rabat



Levels of Structure





الجاوعــــــــة الدوايــــــــة للربــــــاط +₀O∧₀LՀ+ +₀XO₀YI₀I+ | QQ⊖₀E Université Internationale de Rabat





Unit cell

Atoms are arranged in a 3D, making "unit cell"





+.OA.UE+ +.XO.YH.I+ I QQO.E Université Internationale de Rabat



Microstructure

Monocrystalline

- the periodic arrangement of atoms (unit cells) extends throughout the entire sample
- difficult to grow, environment must be tightly controlled
- anisotropic materials

Polycrystalline

- many small crystals or grains
- small crystals misoriented with respect to on another
- several crystals are initiated and grow towards each other
- anisotropic or isotropic materials







The Tension and Compression Test







The Tension and Compression Test



The Stress–Strain Diagram

A curve shows the variation of the strain in function of the stress where the vertical axis represent the stress and the horizontal axis represent the strain

Conventional Stress–Strain Diagram.
True Stress–Strain Diagram

Two stress-strain diagrams for a particular material will be quite similar, but will never be exactly the same. This is because the results actually depend on variables such as:

- \checkmark The material's composition.
- ✓ Microscopic imperfections,
- \checkmark The way it is manufactured,
- \checkmark The rate of loading,
- \checkmark The temperature during the test
- \checkmark The time of the test.





Nominal or **Engineering Stress:** Applied load dividing by the specimen's original cross-sectional area. Here the stress is assumed to be constant over the cross section

and throughout the gauge length.

Nominal or **Engineering Strain:** Strain gauge reading, or The change in the specimen's gauge length dividing by the specimen's original gauge length.

Here the strain is assumed to be constant throughout the region between the gauge points.



الجامعـــــة الدوايـــــــة للربــــــاد @∧₀UՀ+ +₀XO₀YH₀I+ I QQ⊖₀E Jniversité Internationale de Rabat





http://classroom.materials.ac.uk/flash/tensile.swf







Conventional and true stress-strain diagrams for ductile material (steel) (not to scale)

الجاهعــــــــــة الدوليـــــــة للربـــــــاط +₀⊙∧₀⊔Հ+ +₀XO₀YN₀I+ I QQ⊖₀E Université Internationale de Rabat



Elastic Behavior:

Light orange region

The curve is actually a straight line throughout most of this region, so that the stress is proportional to the strain. The material in this region is said to be linear elastic. The upper stress limit to this linear relationship is called the **proportional limit**, If the stress slightly exceeds the proportional limit, the curve tends to bend and flatten out. This continues until the stress reaches the **elastic limit**. Upon reaching this point, if the load is removed the specimen will still return back to its original shape.

Normally for steel, however, the elastic limit is seldom determined, since it is very close to the proportional limit and therefore rather difficult to detect.





Yielding:

Dark orange region

A slight increase in stress above the elastic limit will result in a breakdown of the material and cause it to deform permanently.

This behavior is called **yielding**. The stress that causes yielding is called the **yield stress** or **yield point**, and the deformation that occurs is called **plastic deformation**.

For low carbon steels or those that are hot rolled, the yield point is often distinguished by two values. The **upper yield point** occurs first, followed by a sudden decrease in load-carrying capacity to a **lower yield point**. Notice that once the yield point is reached, then as shown, the specimen will continue to elongate (strain) without any increase in load. When the material is in this state, it is often referred to as being **perfectly plastic**.



الجارعــــــــــة الدوايــــــــة للربـــــــاد @∧ه⊔٤+ +هXOه۲۱۵۱+ I QQOهE Jniversité Internationale de Rabat



Strain Hardening:

Light green region

An increase in load can be supported by the specimen, resulting in a curve that rises continuously but becomes flatter until it reaches a maximum stress referred to as the **ultimate stress**.



الجاوعـــــــــة الدوايـــــــة للربــــــاد O∧oLՀ+ +₀XO₀YN₀I+ I QQO₀E ا+ioXO₀YN₀I+ I niversité Internationale de Rabat Mechanics of Materials (EM3213) M. F. GHANAMEH 2017-2018



School of

Necking:

Dark green region

Up to the ultimate stress, as the specimen elongates, its crosssectional area will decrease. This decrease is fairly uniform over the specimen's entire gauge length; however, just after, at the ultimate stress, the cross-sectional area will begin to decrease in a localized region of the specimen. As a result, a constriction or "neck" tends to form in this region as the specimen elongates further, Here the stress–strain diagram tends to curve downward until the specimen breaks at the **fracture stress**.



الجاوعــــــــــة الدوايـــــــة للربـــــــا ⊙∧ه⊔Հ+ +هXOه۲۷هI+ I QQ⊖هE niversité Internationale de Rabat Mechanics of Materials (EM3213) M. F. GHANAMEH 2017-2018



School of

True Stress–Strain Diagram.

Instead of always using the original cross-sectional area and specimen length to calculate the (engineering) stress and strain, we could have used the actual cross-sectional area and specimen length at the instant the load is measured. The values of stress and strain found from these measurements are called true stress and true strain, and a plot of their values is called the **true stress–strain diagram**.

The conventional and true diagrams are practically coincident when the strain is small. The differences between the diagrams begin to appear in the strain-hardening range, where the magnitude of strain becomes more significant. In particular, there is a large divergence within the necking region



الجاوعــــــــة الدوليــــــة للربــــــا ⊙∧₀UՀ+ +₀XO₀∀II₀I+ I QQ⊖₀E niversité Internationale de Rabat Mechanics of Materials (EM3213) M. F. GHANAMEH 2017-2018



School of

True & conventional Stress–Strain Diagram

Most engineering design is done so that the material supports a stress within the elastic range. This is because the deformation of the material is generally not severe and the material will restore itself when the load is removed. The true strain up to the elastic limit will remain small enough so that the error in using the engineering values of the stress and the strain is very small (about 0.1%) compared with their true values,

This is one of the primary reasons for using conventional stress-strain diagrams.











Ductile Materials:

Any material that can be subjected to large strains before it fractures is called a ductile material. (typical example : mild steel) (also as brass, molybdenum, and zinc), Engineers often choose ductile materials for design because these materials are capable of absorbing shock or energy, and if they become overloaded, they will usually exhibit large deformation before failing.



الجامعــــــة الدوليــــــة للزبــــــاد ©∧₀LՀ+ +₀XO₀YII₀I+ I QQ⊖₀E Iniversité Internationale de Rabat Mechanics of Materials (EM3213) M. F. GHANAMEH 2017-2018



School of

Ductile Materials:

One way to specify the ductility of a material is to report its percent elongation or percent reduction in area at the time of fracture:

- *Percent elongation:* is the specimen's fracture strain expressed as a percent. (for mild steel ≈38%)
- **Percent reduction in area:** is the ratio of reduction in crosssectional area (the subtraction of the area of the neck at fracture from original cross-sectional area) on the specimen's original cross-sectional area. (for mild steel $\approx 60\%$).





In most metals, however, constant vielding will not occur beyond the elastic range (for example aluminum). Actually, this metal often does not have a welldefined yield point, and consequently it is standard practice to define a **yield** strength using a graphical procedure called the offset method. Normally at 0.2% strain so we get for the aluminum the yield strength is (352 MPa).



الجامعــــــة الدوليـــــة للربـــــاط +₀⊙∧₀⊔٤+ +₀⊼O₀۲№۱+ I QQ⊖₀E Université Internationale de Rabat



Brittle Materials.

Materials that exhibit little or no yielding before failure are referred to as **brittle materials**. (typical example : Gray cast iron)

Since the appearance of initial cracks in a specimen is quite random, brittle materials do not have a well-defined tensile fracture stress. Instead the average fracture stress from a set of observed tests is generally reported.





Brittle Materials.

Brittle materials, such as gray cast iron, exhibit a much higher resistance to axial compression, For this any cracks case or imperfections in the specimen tend to close up, and as the load increases the material will generally bulge or become barrel shaped as the strains become larger.









Most materials exhibit both ductile and brittle behavior. For example, steel has brittle behavior when it contains a high carbon content, and it is ductile when the carbon content is reduced.

Also, at low temperatures materials become harder and more brittle, whereas when the temperature rises they become softer and more ductile.



